

Department of Energy

Ohio Field Office Fernald Environmental Management Project P. O. Box 538705 Cincinnati, Ohio 45253-8705 (513) 648-3155



SED 0 9 2002

Mr. James A. Saric, Remedial Project Manager United States Environmental Protection Agency Region V-SRF-5J 77 West Jackson Boulevard Chicago, Illinois 60604-3590

DOE-0700-02

Mr. Tom Schneider, Project Manager Ohio Environmental Protection Agency 401 East 5th Street Dayton, Ohio 45402-2911

Dear Mr. Saric and Mr. Schneider:

TRANSMITTAL OF CERTIFIED FOR CONSTRUCTION (CFC) PACKAGE FOR THE SOUTH FIELD PHASE II GROUNDWATER REMEDIATION MODULE INFRASTRUCTURE

- References: 1. Letter, J. Reising to J. Saric and T. Schneider, "Transmittal of Design for Remediation of the Great Miami Aquifer; South Field Phase II Module," dated May 16, 2002
 - 2. Letter, J. Reising to J. Saric and T. Schneider, "Transmittal of the Project Re-Injection Wells and Additional South Field Monitoring Wells," dated June 10, 2002

This transmittal provides the South Field Phase II groundwater remediation module infrastructure Certified for Construction (CFC) package. Per discussions during recent weekly teleconferences, the CFC package is being forwarded for information. Any comments received which require a change will be incorporated as an addendum to the package.

Proceeding in this manner allows the package to continue through the bidding and award cycle before the close of the fiscal year. This is deemed acceptable as the United States Environmental Protection Agency (USEPA) and Ohio Environmental Protection Agency (OEPA) have already been very much involved in location and installation of the subject extraction and injection wells through their review of the report on the Design for the Remediation of the Great Miami Aquifer; South Field Phase II Module (Reference 1) and the

SEP 0 9 2002

Mr. James A. Saric Mr. Tom Schneider -2-

DOE-0700-02

subsequent review of the Project Specific Plan (PSP) for installation of the South Field Phase II module extraction/re-injection wells and additional South Field monitoring wells (Reference 2).

If you have any questions, please contact Robert Janke at (513) 648-3124.

Sincerely,

FEMP:R.J. Janke

Johnny W. Reising Fernald Remedial Action Project Manager

Enclosure: As Stated

cc w/enclosure:

R. J. Janke, OH/FEMP

A. Murphy, OH/FEMP

T. Schneider, OEPA-Dayton (three copies of enclosure)

G. Jablonowski, USEPA-V, SRF-5J

F. Bell, ATSDR

M. Cullerton, Tetra Tech

M. Shupe, HSI GeoTrans

R. Vandegrift, ODH

AR Coordinator, Fluor Fernald, Inc./MS78

cc w/o enclosure:

R. Greenberg, EM-31/CLOV

N. Hallein, EM-31/CLOV

A. Tanner, OH/FEMP

D. Brettschneider, Fluor Fernald, Inc./MS52-5

D. Carr, Fluor Fernald, Inc./MS2

M. Frank, Fluor Fernald, Inc./MS90

T. Hagen, Fluor Fernald, Inc./MS9

W. Hertel, Fluor Fernald, Inc./MS52-5

M. Jewett, Fluor Fernald, Inc./MS52-5

T. Poff, Fluor Fernald, Inc./MS65-2

ECDC, Fluor Fernald, Inc./MS52-7